


**Figure 2/Video 2.** Off-axis parasternal long-axis view showing the figure of 8 image artifact of the occluder device.



**Figure 3/Video 3.** The occluder device resembles a clover-leaf in this off-axis parasternal long-axis view.

coronal imaging position is necessary to avoid misinterpretations of studies such as malposition or displaced device.

### Conflicts of interest

The authors declare do not have conflicts of interest.

### Ethical disclosures

**Protection of human and animal subjects.** The authors declare that no experiments were performed on humans or animals for this study.

**Confidentiality of data.** The authors declare that they have followed the protocols of their work center on the publication of patient data.

**Right to privacy and informed consent.** The authors declare that no patient data appear in this article.

### References

1. Bertrand PB, Levine RA, Isselbacher EM, et al. Fact or artifact in two-dimensional echocardiography: avoiding misdiagnosis and missed diagnosis. *J Am Soc Echocardiogr.* 2016;29:381-91.
2. Bertrand PB, Grieten L, Smeets CJ, et al. The figure-of-eight artifact in the echocardiographic assessment of percutaneous disc occluders: impact of imaging depth and device type. *Echocardiography.* 2015;32:557-64.